



Photograph
#1

West
Fence



Photograph
#2

West
Fence



Photograph
#3

Corner
West
Fence
&
North
Rear
Fence




Photograph
#4
West
Fence



Photograph
#5
West
Fence



Photograph
#6
West
Fence




Photograph
#7
North
Back
Fence



PHOTOGRAPH # 8 REAR BACK FENCE



PHOTOGRAPH #9 NORTH BEAK BACK FENCE



PHOTOGRAPH #10 NORTH CAROLINA FENCE



PHOTO 06/24/11 NORTH BEAR ROCK FENCE



PHOTOGRAPH #12 NORTH BEAR ROCK FENCE



PHOTOGRAPH #13 NORTH BARK FENCE W → E



PHOTOGRAPH
#14
REAR BACK
FENCE
LINE
E → W



PHOTOGRAPH #15 VIEW FROM MY YARD OVER REAR BACK FENCE



PHOTOGRAPH #12 VIEW DOWN RARE BRACKEN LINE E → W

PHOTOGRAPH #7 VIEW OVER REAR FENCE LINE INTO NEIGHBOR'S YARD



PHOTOGRAPH #18 VIEW DOWN BRAZ RIVER VALLEY W-7E





PHOTOGRAPH #19 NORTHWEST CORNER 5 FEET PENETRATION



PHOTOGRAPH #20 CENTER VIEW OF REAR BACK FENCE



PHOTOGRAPH
#21

BACK
REAR
FENCE

FIVE FOOT
PENETRATION



PHOTOGRAPH #22 BACK REAR FENCE'S FOOT PENETRATION



PHOTOGRAPH #23 CENTER VIEW OF REAR BACK FENCE



PHOTOGRAPH #24 VIEW OF REAR BACK FENCE